Motor controller sensor plug adjust







A0. Prepare the tools.



A1. Release 8 screws of foot deck.(by using H3 hex driver)



A2. Find out the connector with label '2. motor' and '3. hall sensor', then cut off their cable tights.









A3. Unplug the connector with '2. motor' and '3. hall sensor', then try to check if there is anything bended. Adjusted them if needed or bend it a bit to create a better contact.









B0. Then plug them back again to see if the contact issue is fixed.

B1. Screw the foot deck on. **Installation is done.**